




**CENTURY HOME INSPECTIONS**

# Home Inspection Report



**CENTURY HOME INSPECTIONS**

---

**301 W Franklin Street Apartment 2A, Baltimore, MD 21201**

**Inspection Date:**

Saturday, August 25, 2018

**Prepared For:**

**Prepared By:**

Sinnott Enterprises LLC, dba: Century Home Inspections

443-832-5887

century.inspections@gmail.com

**Report Number:**

901


**Inspector:**

Stephen Sinnott

**License/Certification #:**


33186

**Inspector Signature:**



# Interior Is Without Pests

## Subsection Photos



She is kind of a pest

# Electrical Outlets Grounded

## Subsection Photos



Outlet to left of sink does not work

# Hot And Cold Running Water


## Subsection Photos



Water temp should be 110 degrees

# Windows Functioning Properly

## Subsection Photos




Left window in living room will not open

# Exterior Walls Free Of Holes Allowing Weather, Pests To Enter

## Subsection

### Photos



This snuck in